

Bulletin No: 136

Release Date: 16 June 2011

Region: Global

<u>IP500 Digital Station 30A – Expansion Module Software</u>

This Technical Bulletin is to advise customers of a new Release 7 binary file for the IP500 Digital Station "A" Expansion Modules. The new binary file, 9.0(1201) resolves an issue with noise when using a "M" or "T" series telephone connected to port 18 of a DS30A Expansion Module. Avaya recommends that customers experiencing this issue upgrade DS30A Expansion Modules to the 9.0(1201) software.

The binary file can be found in the IP Office 7.0 download section of the Avaya Support Web site:

http://support.avaya.com

Issued by: Avaya SME Customer Product Engineering Support Contact details:-

EMEA/APAC NA/CALA
Tel: +44 1483 308 000 Tel: +1 908 204 4686

Email: gsstier4@avaya.com Email: IPONACALAT4@avaya.com

Internet: http://www.avaya.com
© 2011 Avaya Inc. All rights reserved.